

Electrode Selector

SELECT THE RIGHT ELECTRODE FOR YOUR APPLICATION.



	ļ	AVAILA	BLE SIZ	ZES				FEATURES	APPLICATIONS	POSITIONS
Se	2	2.0	2.5	3.2	4.0	5.0	6.0			
ral Purpo	12P							 > Fast freezing slag > Tolerant to dirty materials > Exceptional vertical down capabilities 	 > General mild steel fabrication > Repair work > General machinery > Agricultural steels & equipment > Wrought iron 	4F 2G 2G 2F 1G-1F
Genei		13	S				 > Very fluid slag > Superior weld appearance > Especially suited to vertical up welding 	 > General mild steel fabrication > Repair work > Trailers 	4F $2G$ $2G$ $2F$ $1G-1F$ $4G$ $3G$ $3F$	

	AVAIL	ABLE SI	ZES				FEATURES	APPLICATIONS	POSITIONS
Low Hydrogen	2.0	2.5	3.2	4.0	5.0	6.0			
	16	TC					 > For carbon & low alloy steels > Easy slag removal > Exceptional arc stability > All positional (except vertical down) 	 > Agricultural steels > Maintenance & repair > Structural steel, stock gates & fencing > Earth moving equipment 	4F 2G 2F 2F 1G-1F
	18	TC					 > Excellent AC arc stability & DC+ transfer > Excellent re-strike > Easy slag removal > For out of position welding 	> Oil & gas > Pipe welding > Structural steel > Mining equipment > Maintenance & repair	4F 2G 2F 1G-1F
	77						 > Exceptionally smooth > All positional (except vertical down) > X-ray quality 	 > Earth moving equipment > Maintenance & general repair work > For critical weld requirements 	4F 4F 4F 2F 1G-1F

Iron Powder	AVAIL	ABLE SI	ZES				FEATURES	APPLICATIONS	POSITIONS
	2.0	2.5	3.2	4.0	5.0	6.0			
		24					 > Excellent slag detachability > Good edge wetting > Positive arc starting & re-striking > Excellent down hand & horizontal position 	 > Large structural steel & repair > Agricultural steels & equipment > Heavy section / thick plate 	2F 1G-1F

HOBART



welding.com.au

Trusted by the best